

SERVICE BULLETIN

September 10, 1984

No. 54

TO: ALL CUSTOMERS

SUBJECT: SIDEWALL UNDULATIONS IN RADIAL PASSENGER TIRES

Attached is a TIRE INFORMATION SERVICE BULLETIN issued by RMA explaining sidewall undulations in radial passenger tires. The bulletin is complete with a photograph of the undulation.

Should you have any questions concerning sidewall appearance, please contact Consumer Relations at 800-854-6288 (in Ohio call 424-4228).

CONSUMER RELATIONS

COOPER TIRE & RUBBER COMPANY

